

Egg. Graphics.

Syllabus

class XII

2016 April - May

i) Isometric Projection - Isometric scale, simple isometric projection, combination.

ii) Drawing of machine parts: Thread profile, Nuts, bolts, studs, rivets and riveted joints, Machine screws and keys
(studs, screws, keys and rivets free hand sketching)
K. K. K.